



# FACILITY COMPLIANCE INSPECTION REPORT

## Division of Waste Management Solid Waste Section

### UNIT TYPE:

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Cleveland PERMIT NO.: SLAS 23-06 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection:** 10/11/13

**Date of Last Inspection:** 8/23/13

### FACILITY NAME AND ADDRESS:

Leonard McSwain Septic Tank  
 1030 Union Church Rd. (SR-1364)  
 Shelby, NC 28150

**GPS COORDINATES:** N: 35.386111° E: - 81.591111°

### FACILITY CONTACT NAME AND PHONE NUMBER:

Leonard McSwain  
 Office: (704) 482-1380

### FACILITY CONTACT ADDRESS:

Leonard McSwain Septic Tank - Office  
 3020 Ramseur Church Rd.  
 Shelby, NC 28150

### AUDIT PARTICIPANTS:

Bill Wagner, Environmental Senior Specialist – Solid Waste Section

### STATUS OF PERMIT:

Current – Issued March 15, 2013

Expires October 1, 2017

### PURPOSE OF SITE VISIT:

Semi-annual compliance inspection and collection of soil samples.

### STATUS OF PAST NOTED VIOLATIONS:

N/A

### OBSERVED VIOLATIONS

None.

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**AREAS OF CONCERN:**

**NONE.**

**ADDITIONAL COMMENTS**

1. The site consists of two land application fields located off the south side of Union Church Road (SR-1364, just east of Yates Road (SR-1821). Field # 1 is the northern most (closed to Union Church Rd.) and Field #2 is the southernmost field.
2. The access road to the application fields was well maintained.
3. Buffers and limits of each field were well marked.
4. Proper signage was displayed at the entrance to the site.
5. Approved setbacks appear to be maintained. (i.e. distances from wells, homes, etc.)
6. There was no evidence of any application of septage outside of the permitted application areas.
7. There were no objectionable odors detected during the inspection.
8. Septage appears to have been properly applied in an even manner with no evidence of any ponding or over application of waste.
9. The cover crop was well established with no bare areas.

Please contact me if you have any questions or concerns regarding this inspection report.



Bill Wagner

Environmental Senior Specialist

***Regional Representative***

Phone: 828-296-4705

<b>Sent on: 10/14/13 to:</b> Leonard McSwain Septic Tank 3020 Ramseur Church Rd. Shelby, NC 28150		Email		Hand Delivery	<b>X</b>	US Mail		Certified No. _____
--	--	-------	--	------------------	----------	------------	--	---------------------

ec: Tony Gallagher, Septage & Land Application Branch – Branch Head  
Jason Watkins, Solid Waste Section – Western District Supervisor  
Liz Patterson, Solid Waste Section